

Technical information

Trouble shooting – drilling

C166-C169

Technical information – drilling

C170-C177

Forms nonstandard order

C178-C182

C

A

Turning

B

Milling

C

Drilling






D

Technical
Information

E

Index

Trouble shooting – solid carbide drills

Error	Reason	Countermeasure
Oversized holes 	<ul style="list-style-type: none"> – Insufficient clamping of workpiece and/or tool – Large radial run out – Point relief is off centre 	<ul style="list-style-type: none"> – Use precision clamping – Reduce spindle play – Check and adjust clamped drill
	<ul style="list-style-type: none"> – Asymmetric point angle – Large radial run out – Point relief is off centre 	<ul style="list-style-type: none"> – Regrind drill – Check quality of regrinding
Irregular hole size 	<ul style="list-style-type: none"> – Asymmetric point angle – Large radial run out – Point relief is off centre – High wear 	<ul style="list-style-type: none"> – Use precision clamping – Reduce spindle play – Check and adjust clamped drill
	<ul style="list-style-type: none"> – Insufficient clamping of work piece and/or tool – Large radial run out – Point relief is off centre – High wear 	<ul style="list-style-type: none"> – Use precision clamping – Reduce spindle play – Check and adjust clamped drill
	<ul style="list-style-type: none"> – Feed rate too high 	<ul style="list-style-type: none"> – Reduce feed rate
	<ul style="list-style-type: none"> – Insufficient coolant 	<ul style="list-style-type: none"> – Increase amount of coolant or change coolant supply
Low position accuracy 	<ul style="list-style-type: none"> – Insufficient clamping and spindle positioning – Large radial run out of spindle 	<ul style="list-style-type: none"> – Improve positioning of machine – Use precision clamping – Calibrate spindle – Check and adjust clamped drill
	<ul style="list-style-type: none"> – The feed direction is not vertical to the workpiece surface 	<ul style="list-style-type: none"> – Adjust feed rate vertically to workpiece surface
	<ul style="list-style-type: none"> – Tool isn't aligned with centre of spindle (lathe machines) 	<ul style="list-style-type: none"> – Centre the tool
Bad drill run out 	<ul style="list-style-type: none"> – High tool wear 	<ul style="list-style-type: none"> – Regrind drill
	<ul style="list-style-type: none"> – Poor drill accuracy 	<ul style="list-style-type: none"> – Improve positioning of drill
	<ul style="list-style-type: none"> – Asymmetric point angle – Large radial run out – Point relief is off centre 	<ul style="list-style-type: none"> – Regrind drill – Check quality of regrinding
	<ul style="list-style-type: none"> – Insufficient tool stability 	<ul style="list-style-type: none"> – Improve stability of tool
Inaccurate hole (roundness) 	<ul style="list-style-type: none"> – Asymmetric point angle – Large radial run out – Point relief is off centre – High wear 	<ul style="list-style-type: none"> – Regrind drill – Check quality of regrinding
	<ul style="list-style-type: none"> – Insufficient clamping of work piece and/or tool – Large radial run out of spindle 	<ul style="list-style-type: none"> – Use precision clamping – Calibrate spindle – Check and adjust clamped drill
	<ul style="list-style-type: none"> – Clearance angle too large 	<ul style="list-style-type: none"> – Regrind the drill
	<ul style="list-style-type: none"> – Insufficient tool stability 	<ul style="list-style-type: none"> – Improve tool stability

A

Turning

B

Milling

C

Drilling





D

Technical Information

E

Index

Trouble shooting – solid carbide drills

Error	Reason	Countermeasure
Bad surface quality	– Bad drill regrinding	– Improve regrinding
	– Insufficient amount of coolant or coolant method	– Change coolant supply – Increase amount of coolant
	– Insufficient clamping – Large radial run out of spindle	– Use precision clamping – Calibrate spindle
	– Feed rate too high	– Reduce feed rate
	– High wear of cutting edge – High welding	– Regrind drill – Use a coated drill
	– Bad chip removal	– Chose a suitable drill (with an accordingly flute, helical angle etc.) – Adjust cutting speed (reduce feed rate, etc.)
Bad cylindricity 	– No symmetrical point angle – Large radial run out (drilling) – Centre insert is off centre – Large cutting edge wear – Feed rate too low	– Regrind drill – Check regrind – Increase feed rate
Breakage of drill 	– Insufficient clamping of tool and/or workpiece – Clearance angle too small – Feed rate too high – Excessive wear – Chip jamming – Drilling in uneven surfaces	– Improve stability of tool and clamping of workpiece – Use a drill with bigger clearance angle or regrind – Reduce feed rate – Regrind drill – Chose a suitable drill (considering flute geometry, helical angle, etc.) – Adjust cutting speed – Reduce feed rate – Increase rigidity of drill and clamping of machine and workpiece – Use drill with sharp centre insert – Pre-drill a centre hole – Create a straight surface (e.g. with solid carbide milling cutter) – Use a guide bush or bush plate
Chipping on the drill 	– Hard surface or blow holes – Feed rate too high – Insufficient coolant	– Check material and chose suitable grade – Change cutting conditions (cutting speed, feed rate or machining method) – Reduce feed rate – Improve/increase coolant supply
Chipping on the cutting edge 	– Poor clamping – Large radial run out – Cutting speed and feed rate too high – Clearance angle too large	– Use a more precise clamping device – Adjust the spindle – Reduce cutting speed and feed rate – Use a drill with smaller clearance angle or regrind

A

Turning

B

Milling

C

Drilling


D

Technical Information

E

Index

Trouble shooting – solid carbide drills

Error	Reason	Countermeasure
Excessive wear 	– Overdue regrinding	– Regrind in time
	– Drill tip not in centre position	– Adjust drill with centre of spindle
	– Cutting speed too high	– Reduce cutting speed
	– Cutting angle not suitable	– Chose right cutting angle
	– Material not suitable	– Chose suitable material
	– Insufficient cooling	– Use suitable cooling
Wear and chipping on point relief	– Feed rate too high	– Reduce feed rate
	– Cutting angle not suitable	– Chose right cutting angle
	– Material not suitable	– Chose suitable material
	– Clearance angle too small	– Regrind drill
Breakage on margin	– Guide bush too large	– Change guide bush
Built up edge on margin	– High wear and heat	– Regrind drill
	– Insufficient cooling	– Change cooling method
	– Wrong coolant	– Change coolant
	– Workpiece material is too soft	– Use drill with smaller clearance angle
High vibrations	– Clearance angle too large	– Regrind drill
	– Drill stability too low	– Improve stability
Swarf clogs the drill	– Long chips – Chip removal not fluent	– Optimise cutting data – Change drill or adjust machine
One-side wear	– Drill tip not centred	– Adjust drill with centre of spindle
	– Poor clamping	– Improve drill clamping – Check concentricity

A

Turning

B

Milling

C

Drilling





D

Technical Information

E

Index

Trouble shooting – PC series

Machining	Recommendation								
<p>Sloped surface</p> 	<p>– Inclined surfaces should be pre-machined (chamfering).</p> 								
<p>Inclined surface</p> 	<p>– Reduce feed rate accordingly.</p>  <table border="1" data-bbox="995 987 1430 1111"> <thead> <tr> <th>Inclination angle</th> <th>Max. feed rate</th> </tr> </thead> <tbody> <tr> <td>1°</td> <td>80%</td> </tr> <tr> <td>2°</td> <td>50%</td> </tr> <tr> <td>3°</td> <td>30%</td> </tr> </tbody> </table>	Inclination angle	Max. feed rate	1°	80%	2°	50%	3°	30%
Inclination angle	Max. feed rate								
1°	80%								
2°	50%								
3°	30%								

A

Turning

B

Milling

C

Drilling

D





Technical
Information




E

Index

Solid carbide drills







Operation notes

Correct drill clamping	Max. drilling length	Radial run-out	Wrong drill clamping
 <p>Adjusting screw</p> <p>Use precision collets</p>	 <p>$H = 1,5 \times d1$</p>	 <p>Radial run-out <math>< 0.02 \text{ mm}</math></p>	 <p>Don't clamp on the drill flutes.</p>

External coolant method	Internal coolant method	
		
<p>The coolant liquid should shoot to the end and the centre of the drill as shown in the figure.</p>	<p>Coolant pressure is about 0.5–1 mpa (coolant pressure is 2–3 mpa when the diameter is less than 5 mm), coolant volume: 1.5–4 L/min</p>	

Handling of coolants:

1. Small chip particles and dust can cause jamming in the oil hole. A fine mesh filter should be used.
2. Dirt and dust particles will adhere to the oil hole and lead to unsmooth coolant flow. Regularly change the coolant. Please ensure proper coolant supply.

Interrupted cutting	Thin work pieces	Stepped holes	Burrs and work piece chippings on exit
 <p>Reduce the feed rate when drilling interrupted cut.</p>	  <p>If bending occurs, add a supporter.</p>	 <ul style="list-style-type: none"> – First drill the larger hole, then the smaller hole. – We can offer multiple step and chamfer drills on request. 	 <ul style="list-style-type: none"> – Reduce the feed rate approx. by half when the drill exits. – Use a drill with a different point angle.
 <p>Machine a countersink with an end mill prior to drilling.</p>			

A

Turning

B

Milling

C

Drilling

D


Technical Information

E

Index

Solid carbide drills

Terminology



- 1. Drilling diameter
- 2. Chamfer
- 3. Point angle
- 4. Clearance angle
- 5. Chip pocket
- 6. Shank
- 7. Shank diameter
- 8. Shank length
- 9. Overall length
- 10. Flute length
- 11. Helical angle

- a. Margin width
- b. Body clearance
- c. Land width
- d. Primary cutting edge

Cutting edge type

Shape	(Conical)	(Dual flats)	(Centring tip)
Shape			
Features	<ul style="list-style-type: none"> - The flank face is conical and the clearance angel increases toward the centre of drill. - Wide applications, commonly used both for soft and hard materials. 	<ul style="list-style-type: none"> - The flank face is dual flats, to facilitate cutting and initial entering. - Often used for small diameter drills. 	<ul style="list-style-type: none"> - This shape has two-stage point angles for perfect centring capabilities and reduces burrs. - It is the first choice for drilling thin plate.

A

Turning

B

Milling

C

Drilling

D

Technical Information

E

Index

A

Turning

Solid carbide drills

Drill specification and cutting parameters

Chip pocket	The chip pocket ensures that the chips are removed out of the hole during processing.
Helical angle	The helical angle describes the pitch of the flute. It's specified according to the to be machined material. hardened materials small ← helical angle → large tough materials
Cutting edge length or spiral length	The cutting edge length needs to be specified according to the drilling depth, guide bushing length and the whole regrinding length. The larger the helical angle, the lower the stability. Since it greatly influences the tool life, it should be as small as possible. The recommended min. spiral length is the drilling depth plus 1.5 times of the hole diameter.
Point angle	Generally the point angle is 140°, for special applications it should be set differently. tough materials, easy to machine small ← point angle → large hardened materials and high-performance drilling
Core diameter	The core diameter is an important factor and influences the stability and the chip flow. low axial cutting force low stability for easy to machine materials] small ← core diameter → large [high axial cutting force high stability for hardened materials or cross holes
Chamfer width	The chamfer width influences the guidance and friction of the drill during machining. low friction and bad drill guidance] small ← chamfer width → large [high friction and good drill guidance
Back taper	The drill diameter is slightly reduced from cutting edge to shank to reduce friction during machining.
Body clearance	The area behind the chamfer width. The body clearance is necessary to reduce friction during machining.

B


Milling

C

Drilling

Deep hole drilling

1 Preparation of the pilot hole with 1534SP03C*




- Point angle of pilot drill must be bigger than SL drill.
- Diameter of pilot drill must be 0.01–0.04 mm bigger than SL drill.
- The pilot hole should be 1–3×D.

2 Entering the pilot hole with SL drill



- Entering the pilot hole with low cutting speed. (VC: 20–30 m/min)
- Stop 1–3 mm before end of pilot hole. (Vf = 0)
- Increase cutting speed up to recommended parameter and then start drilling at feed rate.

3 Manufacturing the deep hole



- Drilling with suitable cutting speed and feed rate.
- In case of cross holes feed rate should be reduced to 0.05 mm/rev..

4 Pulling out the drill



- After reaching the required depth reduce the cutting speed (VC: 20–30 m/min) and pull out the drill at high feed rate. (Vf: 2000 mm/min)

D


Technical Information

E

Index

Solid carbide reamers

Terminology



- 1.Nominal diameter
- 2.Chamfer length
- 3.Entry angle
- 4.Cutting edge length
- 5.Shank diameter
- 6.Total length

- a.Cutting edge thickness
- b.Core diameter

Reaming is semi-finishing and finishing of a previously formed hole within a narrow tolerance for higher surface quality, perfect roundness, cylindricity, etc.. To achieve a precisely reamed hole, the right choice of reamer and reamer diameter is important. In addition to that, the bore tolerance, the material and the machining conditions need to be taken into account. Furthermore the bore quality is strongly influenced by the radial run-out of the cutting tool.

<p>Diameter tolerance/Allowance</p>	<p>Cylindricity</p>	<p>Straightness</p>
<p>Roundness</p>	<p>Vertical deviation</p>	<p>Off centre</p>

A

Turning

B

Milling

C

Drilling

D

Technical Information

E

Index

Trouble shooting – solid carbide reamers

Problem	Solution
Oversized hole	<ul style="list-style-type: none"> – Reduce the diameter of the reamer. – Check concentricity of the reamer and hole. – Check the radial run-out of the reamer. – Check the shank of the reamer for scratches. – Select a suitable coolant. – Adjust the cutting parameters.
Hole too small	<ul style="list-style-type: none"> – Increase the diameter of the reamer. – Reduce the cutting speed. – Reduce allowance. – Regrind or replace the reamer. – Ensure sufficient cooling.
Poor hole roundness and straightness	<ul style="list-style-type: none"> – Guarantee concentricity of the reamer chamfer. – Reduce overhang. – Check radial run-out after the reamer is clamped. – Adjust concentricity of the reamer and hole. – Check and ensure drill geometry.
Poor surface quality	<ul style="list-style-type: none"> – Reduce the cutting speed. – Ensure correct reaming allowance. – Check the cutting chamfer length of the reamer for wear and built-up edge. – Ensure stability of the machine, tool holder and reamer. – Chose the reamer according to the application. – Check the hole allowance.
Poor bore quality	<ul style="list-style-type: none"> – Pull out the reamer in cutting direction. – Reduce the cutting speed. – Use reamers with more teeth. – Check for concentricity and radial run-out. – Improve coolant supply. – Chose the optimal coolant lubrication.
Reamer breakage and thermal damage	<ul style="list-style-type: none"> – The guide chamfer is insufficient. Check the drill and drilling axis. – Adjust machining allowance. – Ensure sufficient coolant supply. – Adjust the cutting speed and feed rate. – Improve the stability of the machine, the tool holder and the cutting tool. – Change or regrind the cutting tool if the cutter wear is too high.
Damage on reamer shank	<ul style="list-style-type: none"> – Check clamping sleeve and tool holder for damage.
Short tool life	<ul style="list-style-type: none"> – Check coolant supply. – Change from straight fluted to helical fluted reamers. – Check all factors affecting machining precision.
Scratched hole surface	<ul style="list-style-type: none"> – Check the cutting edge for built-up edges and if necessary correct the cutting data. – Improve clamping of the workpiece.
Trumpet-shaped entry hole	<ul style="list-style-type: none"> – Improve clamping of the workpiece. – Check radial run-out of the clamped reamer. – The centre of the reamer may not be aligned with the centre of the hole. Adjust concentricity.

A

Turning

B

Milling

C

Drilling

D

Technical Information

E

Index

Solid carbide thread formers

What is thread forming?

The material fibres aren't severed but compressed at the base of the thread. This is why no material is lost unlike when thread cutting.


Advantages of thread forming:

- The thread is formed much more precisely.
- The thread is more resilient.
- The threads have a very smooth surface.
- Higher rotation speeds and feed rates possible than in thread cutting.
- Longer tool life increases the productivity.


Disadvantages of thread forming:

- Higher requirements on the hole tolerance.
- Can't be used as hand tool.
- Greater heat build-up than in thread drilling.
- Limited material choice.
- Often the use of a release agent is necessary.

Thread formers should be used in materials with good cold formability. Next to steel, stainless steel and aluminium alloys, these include light metals and light metal alloys with a yield strength of 1200 N/mm². Basically, all long-chipping materials are suitable.



Fibre orientation after thread cutting



Fibre orientation after thread forming

A

Turning

B

Milling

C

Drilling

D

Technical Information

E


Index

A

Solid carbide taps

Terminology


Turning




- 1.Thread length
- 2.Neck diameter
- 3.Square head length
- 4.Total length

B

Milling



Chamfer and thread profile





- a.Core diameter
- b.Cutting edge thickness
- c.Chip pocket

- d.Chamfer length
- e.Thread profile angle
- f.Pitch
- g.Chamfer angle

C

Drilling

Chip space and application

Chip space type	Features	Application
 Helical flute tap	<ul style="list-style-type: none"> - Helical flute - No chips inside the hole - Good entering performance - Simple centring 	<ul style="list-style-type: none"> - For long-chipping materials - Suitable for blind holes - Usage in holes with groove
 Straight flute tap	<ul style="list-style-type: none"> - Straight flute - Stable cutting edge - Easy regrinding 	<ul style="list-style-type: none"> - For hard machining - For short-chipping materials - For through holes and blind holes - For wear material

D


Technical Information

E

Index

Solid carbide thread milling cutters

Solid carbide thread milling cutters with cylindrical shank – example



A

Turning

B

Milling

C

Drilling

D

Technical Information

E

Index

Nonstandard – solid carbide drills

A

Turning

<p>Name/Company:</p> <p>Address:</p> <p>Tel.:</p> <p>Fax:</p> <p>E-Mail:</p>	 <div style="text-align: right;">  <small>Scan for PDF</small> </div> <p>Wanheimer Str. 57 40472 Düsseldorf, Deutschland</p> <p>Fax: +49-(0)211-989240-111 E-Mail: technik@zccct-europe.com</p>
--	--












B

Milling

Material		Twist drill series		
Material		SU <input type="checkbox"/>	SH <input type="checkbox"/>	SL <input type="checkbox"/>
Tensile strength (N/mm ²)		SUK <input type="checkbox"/>		SLK <input type="checkbox"/>
Hardness		ST <input type="checkbox"/>	SC <input type="checkbox"/>	PA <input type="checkbox"/>


C

Drilling

Cooling	Tool holder type	Coating						
 External <input type="checkbox"/>  Internal <input type="checkbox"/>	<p>DIN6535</p> <table border="1"> <tr> <td></td> <td></td> <td></td> </tr> <tr> <td>Form HA <input type="checkbox"/></td> <td>Form HB <input type="checkbox"/></td> <td>Form HE <input type="checkbox"/></td> </tr> </table>				Form HA <input type="checkbox"/>	Form HB <input type="checkbox"/>	Form HE <input type="checkbox"/>	Yes <input type="checkbox"/> No <input type="checkbox"/>
								
Form HA <input type="checkbox"/>	Form HB <input type="checkbox"/>	Form HE <input type="checkbox"/>						

D

Technical Information





E



Index



Remarks:	
Order quantity:	Expected delivery date:
Date:	Confirmation:




Nonstandard – solid carbide step drills

Name/Company:	 ZCC-CT	 <small>Scan for PDF</small>
Address:		
Tel.:		
Fax:		
E-Mail:		
	Wanheimer Str. 57 40472 Düsseldorf, Deutschland	
	Fax: +49-(0)211-989240-111 E-Mail: technik@zccct-europe.com	

Material	
Material	
ensile strength (N/mm ²)	
Hardness	


Machining information	
 Chamfering <input type="checkbox"/>	 Stepped hole <input type="checkbox"/>

Cooling	
	External <input type="checkbox"/>
	Internal <input type="checkbox"/>

Tool holder type		
DIN6535		
 Form HA <input type="checkbox"/>	 Form HB <input type="checkbox"/>	 Form HE <input type="checkbox"/>

Twist drill series	
SU <input type="checkbox"/>	ST <input type="checkbox"/>
SUK <input type="checkbox"/>	
PC <input type="checkbox"/>	

Coating	
Yes <input type="checkbox"/>	
No <input type="checkbox"/>	



Remarks:	
Order quantity:	Expected delivery date:
Date:	Confirmation:

Nonstandard – solid carbide three-lips drills




A

Turning

<p>Name/Company:</p> <p>Address:</p> <p>Tel.:</p> <p>Fax:</p> <p>E-Mail:</p>	 <div style="text-align: right;">  <small>Scan for PDF</small> </div> <p>Wanheimer Str. 57 40472 Düsseldorf, Deutschland</p> <p>Fax: +49-(0)211-989240-111 E-Mail: technik@zccct-europe.com</p>
--	--



B

Milling

Material		Tool holder type		
Material		DIN6535		
ensile strength (N/mm ²)				
Hardness		Form HA	Form HB	Form HE
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


C

Drilling

Cooling		Coating	
	External <input type="checkbox"/>	Yes <input type="checkbox"/>	No <input type="checkbox"/>
	Internal <input type="checkbox"/>		

D

Technical Information





E



Index




Remarks:	
Order quantity:	Expected delivery date:
Date:	Confirmation:



Nonstandard – solid carbide reamers


Name/Company: Address: Tel.: Fax: E-Mail:	 Wanheimer Str. 57 40472 Düsseldorf, Deutschland Fax: +49-(0)211-989240-111 E-Mail: technik@zccct-europe.com
--	---


Scan for PDF

Material		Coating	Cooling
Material		Yes <input type="checkbox"/>	 External <input type="checkbox"/>
Tensile strength (N/mm ²)		No <input type="checkbox"/>	 Internal <input type="checkbox"/>
Hardness			

Helix angle		
	Right <input type="checkbox"/>	
	Straight <input type="checkbox"/>	
	Left <input type="checkbox"/>	

Machining information	
 Through hole <input type="checkbox"/>	 Blind hole <input type="checkbox"/>



Remarks:	
Order quantity:	Desired delivery date:
Date:	Signature:

A
Turning

B
Milling

C
Drilling

D
Technical Information

E
Index

Nonstandard – solid carbide taps and thread formers



A

Turning

Name/Company: Address: Tel.: Fax: E-Mail:	 Wanheimer Str. 57 40472 Düsseldorf, Deutschland Fax: +49-(0)211-989240-111 E-Mail: technik@zccct-europe.com	 <small>Scan for PDF</small>
--	---	--






B

Milling

Material		Coating	Cooling
Material		Yes <input type="checkbox"/>	 External <input type="checkbox"/>
Tensile strength (N/mm ²)		No <input type="checkbox"/>	 Internal <input type="checkbox"/>
Hardness			

C


Drilling

Helix angle	Machining information	Thread profile
 Straight <input type="checkbox"/>  Right <input type="checkbox"/>	 Through hole <input type="checkbox"/>  Blind hole <input type="checkbox"/>	Thread angle = 60°  Pitch p = <input type="text"/>

Tool type
Tap <input type="checkbox"/>
Thread former <input type="checkbox"/>

D

Technical Information



E

Index

Remarks:	
Order quantity:	Desired delivery date:
Date:	Signature: