## **Cycle time left?**

Fill it with 100% certainty!



DIATES



>> 100% Inprocess measurement with DIATEST BMD bore gauges - in your **CNC** machine!

## Whether turning, milling, grinding -

- > The plug gauge BMD is located in the tool changing system of the CNC machine.
  - Standard tool holders can be used for various diameters
    - No conversion of the CNC machine to measured value display - Integration into DIAWIRELESS real radio network
      - Very high repeatability accuracy
        - Floating holder for compensating positioning errors
          - > The following BMD sizes are possible: from 3.95 to 100 mm
            - Independent of machine manufacturer
              - Less human intervention required, less rework, special releases or rejects

⊙I)) INDUSTRIE 4.0

Measuring in the process -100 % safety in the process

## >> Please contact us!

**Automated** 

measurement

in CNC

machines

TNL32-9



Kalibrieren

🕧 🖸 😃 25ka 🏶 www.maxvalue.co.th







Schottener Weg 6 D-64289 Darmstadt Germany

**4** +49 61519790 www.diatest.com











