

วงจรวงล้อเสี่ยงโชค ชุดนี้เป็นวงจรที่แตกต่างจากวงจรทั่วไปคือจะใช้
มอเตอร์ในการหมุนแทนที่ใช้หลอด LED เป็นตัวแสดงผล ซึ่งจะมีข้อดีตรงที่
เราสามารถนำไปคัดแปลงแบ่งช่องขนาดเล็กหรือใหญ่ใค้ตามต้องการ โดยที่
แบบที่เป็นหลอด LED จะไม่สามารถทำได้ นอกจากนั้นวงจรนี้ยังได้ศึกษาการ
ควบคุมการทำงานของมอเตอร์ จากหมุนเร็วและช้าลงเรื่อยๆ และ หยุด ที่
ตำแหน่งใดตำแหน่งหนึ่งอีกด้วย ข้อดีอีกอย่างหนึ่งของวงจรนี้ ไม่จำเป็น ต้อง
มีสวิตช์เปิดปิดวงจร เพราะว่าเมื่อมอเตอร์หยุดหมุนแล้ว วงจรแทบจะไม่กิน
กระแสไฟฟ้าเลย

<u>ข้อมูลูด้านเทคนิค</u>

- -ไฟเลี้ยงวงจร 3-6VDC
- กินกระแสสูงสุดประมาณู 40 mA
- สามารถปรับระยะเวลาได้
- ขนาดแผนวงจรพิมพ ์แสดงผล :2.5 x2.8 นิ้ว

<u>การทำงานของวงจร</u>

ทรานซิสเตอร์ TR1, TR2 ต่อเป็นวงจรขยายกระแสแบบคาร์ลิงตัน (คูรูปที่ 1) เมื่อยังไม่มีการกคสวิตซ์ TR1 และ TR2 จะยังไม่สามารถนำกระแส ไฟได้ มอเตอร์จึงไม่หมุน เมื่อเรากคสวิตซ์ แรงคันไฟจะไปเก็บไว้ที่ C1 และ แรงคันไฟอีกทางหนึ่งจะส่งผ่าน R1 ไปเข้าขาเบสของ TR1 ทำให้ TR1 และ TR2 ทำงาน ส่งผลให้มอเตอร์ทำงานและหมุนตามไปค้วย เมื่อปลอยสวิตซ์ แรงคันไฟที่เก็บไฟที่ C1 จะค่อยๆลคลง โดยไหลผ่านทาง R3 VR1 ลงกราวค์ และส่วนหนึ่งส่งผ่าน R1 ไปเข้าขาเบสของ TR1 ทำให้ TR1 และ TR2 ทำงาน ส่งผลให้มอเตอร์ยังทำงาน และ หมุนตามไปค้วย แต่การหมุนของมอเตอร์จะ ค่อยๆ ลคลงไปเรื่อยๆ ตามการคายประจุของ C1 เมื่อแรงคันที่ C1 ลคลงต่ำ ถึงจุดหนึ่ง จะทำให้ TR1 และ TR2 ไม่สามารถทำงานได้ ส่งผลให้มอเตอร์หยุด ทำงานตามไปด้วย

การประกอบวงจร

การประกอบวงจร ให้ดูรูปที่ 2 และ 3 จะแสดงการดูขั้วและการใส่ อุปกรณ์ต่างๆไว้ การประกอบให้เริ่มจากอุปกรณ์ที่ตัวที่มีความสูงน้อยที่สุด กอน โดยเริ่มจาก ตัวตานทาน สวิตซ์ ทรานซิสเตอร์ เกือกมา และตัวเก็บ ประจุ สำหรับคาปาซิเตอร์แบบอิเล็คโตไลต์ จะต้องดูขั้วให้ถูกต้องค้วย หลัง จากนั้นให้ต่อสายที่จุด M + - ไปที่ขั้วของมอเตอร์ ต่อไปจะเป็นขั้นตอนใน การใส่มอเตอร์ เข้าแผนปริ้นต์ โดยใช้ไขควงขันนอตสองตัวที่ข้างมอเตอร์ออก ก่อน แล้วลอยอืดมอเตอร์เข้ากับแผนปริ้นต์ในตำแหน่งที่ขันน้อตออกตอนก่อน หน้านี้ และยึดลูกศรพลาสติกเข้ากับมอเตอร์ให้เรียบร้อย

การทดสอบวงจร

ให้จายไฟเข้าวงจร ตอนนี้มอเตอร์จะ ไม่หมุน ให้กคสวิตซ์ มอเตอร์จะ หมุนไปทางขวามือ เมื่อปล่อยสวิตซ์มอเตอร์จะก่อยๆหมุนซ้าลงและหยุดใน ที่สุด หากทดลองแล้ว มอเตอร์หมุนไปทางซ้าย แสดงวาต่อสายมอเตอร์ผิด ด้าน ให้บัดกรีสายมอเตอร์ใหม่ให้ถูกต้อง แล้วทดลองใหม่ ถ้าวงจรทำงานได้ ตามที่กล่าวมาข้างต้นก็สามารถนำไปใช้งานได้เลย

การนำไปใช้งานกับแผ่นบอร์ดอื่น

หากต้องการนำไปใช้กับแผนบอร์คที่มีขนาดใหญ่ขึ้น สามารถถอด มอเตอร์ไปใส่บอร์คที่ต้องการ แล้วต่อสายมอเตอร์ให้ยาวขึ้น ในส่วนของลูก สรพลาสติก ถ้าแผนบอร์คไม่ใหญ่มากให้ต่อก้านให้ยาวขึ้นได้ แต่ถ้าบอร์คที่ ใหญ่มากจะต้องหาวัสดุที่น้ำหนักไม่มากมาทำก้านลูกสรขึ้นมาใหม่

Wheel of Fortune วงถือเสี่ยงโชค CODE 1915



This Wheel of Fortune circuit is unique compared to traditional circuits, as it uses a motor for spinning instead of LEDs for display. This offers the advantage of adjustable segment sizes, which is not possible with LED-based designs. Additionally, this circuit explores motor control, enabling the motor to spin quickly at first, then gradually slow down and stop at a specific position. Another benefit of this circuit is that it doesn't require an on-off switch, as it consumes very little power when the motor stops spinning.

Technical Specifications:

- Operating Voltage: 3-6VDC
- Maximum Current Consumption: Approximately 40 mA
- Adjustable Timing
- PCB Size: 2.5 x 2.8 inches

Circuit Operation:

Transistors TR1 and TR2 are connected in a Darlington configuration for current amplification. (See Figure 1) When the switch is not pressed, TR1 and TR2 cannot conduct current, so the motor does not spin. When the switch is pressed, the voltage is stored in capacitor C1 and also sent through resistor R1 to the base of TR1, causing TR1 and TR2 to conduct, thus powering the motor. When the switch is released, the voltage stored in C1 gradually discharges through R3 and VR1 to ground, while part of it is sent through R1 to the base of TR1, allowing TR1 and TR2 to continue operating and keep the motor spinning. The motor's speed will gradually decrease as C1 discharges until TR1 and TR2 can no longer conduct, causing the motor to stop.

Assembly Instructions:

Refer to Figures 2 and 3 for the correct orientation and placement of components. Begin assembly with the shortest components first, such as resistors, switches, transistors, potentiometers, and capacitors. For electrolytic capacitors, ensure correct polarity. After assembling these components, connect the points marked M + - to the motor terminals. Next, attach the motor to the PCB by removing the two screws on the side of the motor, positioning the motor on the PCB where the screws were removed, and securing it with the screws. Finally, attach the plastic arrow to the motor.

Testing the Circuit:

Apply power to the circuit; the motor should not spin initially. Press the switch, and the motor should spin to the right. When the switch is released, the motor should gradually slow down and stop. If the motor spins to the left, reverse the motor wires and test again. If the circuit works as described, it is ready for use.

Using the Circuit with Other Boards:

If you need to use this circuit with a larger board, you can detach the motor and mount it on the desired board, extending the motor wires as needed. For the plastic arrow, extend its shaft for larger boards. If the board is significantly larger, consider using a lightweight material to make a new arrow shaft





