

TEST REPORT

No. : SHIN2107047164CM

Date : Aug 06, 2021

Page: 1 of 4

scan to see the report



SHIN2107047164CM

CUSTOMER NAME: K.O.H. INTERNATIONAL CO., LTD
ADDRESS: 45 MOO 1 TUMBON BORNGERN AMPHUR LADLUMKAEW,
PRATHUMTHANEE 12140

Sample Name : BOARD RETAINING COUPLER
Product Specification : 48.3*48.3
Buyer : K.O.H. International Co.,Ltd
Material and Mark : Q235
Others : IPT64009/7

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Test Required : Failure Force
Ref. Standard : Provided by Client
Date of Receipt : Jul 08, 2021
Testing Start Date : Jul 08, 2021
Testing End Date : Aug 06, 2021
Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical
Service (Shanghai)Co., Ltd.

Ziven Wang

Ziven Wang
Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8387 1443, or email: CN.Doccheck@sgs.com
No.89, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319 t:(86-21)61196300 f:(86-21)61191853/68183920 www.sgsgroup.com.cn
中国·上海·浦东康桥东路1159弄69号 邮编: 201319 t:(86-21)61196300 f:(86-21)61191853/68183920 e sgs.china@sgs.com

TEST REPORT

No. : SHIN2107047164CM

Date : Aug 06, 2021

Page: 2 of 4

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Failure Force	Provided by Client	See Result	/


Note:

Pass : Meet the requirements;

Fail : Does not meet the requirements;

/ : Not Apply to the judgment.

Original Sample Photo(s):



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained herein reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8397 1443, or email: CN.Doccheck@sgs.com

No.89, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319 t:(86-21)61196300 f:(86-21)61191853/68183920 www.sgs.com.cn
 中国·上海·浦东康桥东路1159弄69号 邮编:201319 t:(86-21)61196300 f:(86-21)61191853/68183920 e: sgs.china@sgs.com

TEST REPORT

No. : SHIN2107047164CM

Date : Aug 06, 2021

Page: 3 of 4

Test Item: Failure Force

Test Method: Provided by Client

Test Condition:

Specimen: Board Retaining Coupler, 5pcs

Test Procedure:

1. Install the sample to simulate the conditions of actual practice.
2. Assemble a $\Phi 48.3$ mm solid bar horizontally to the clamp with a tighten torque of 50 N.m.
3. Apply a compression load at the rate of 2mm/min to the solid bar at two points, which are 75mm equidistant from the center of clamp, until the failure occurs, or the load cannot be increased usefully.
4. Record the maximum test load and failure mode.

Test Result:

Sample No.	Maximum Test Load (kN)	Failure Mode
1	40.83	The board was deformed.
2	40.83	The board was deformed.
3	40.42	The board was deformed.
4	41.82	The board was deformed.
5	39.90	The board was deformed.



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Documents.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing/inspection report & certificate, please contact us at telephone: (86-755) 8397 1443, or email: CN.Doccheck@sgs.com

No.89, Block 1150, East Kang Qiao Road, Pudong District, Shanghai, China. 201319 t:(86-21)61196300 f:(86-21)61191853/66183920 www.sgs.com.cn
中国·上海·浦东康桥东路1159弄69号 邮编: 201319 t:(86-21)61196300 f:(86-21)61191853/66183920 e: sgs.china@sgs.com


TEST REPORT

No. : SHIN2107047164CM

Date : Aug 06, 2021

Page: 4 of 4

Test Photo(s):



***** End of report *****



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <http://www.sgs.com/en/Terms-and-Conditions.aspx> and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at <http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

No.55, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China. 201319 t:(86-21)61196300 f:(86-21)61191853/68183920 www.sgsgroup.com.cn
 中国·上海·浦东康桥东路1159弄69号 邮编: 201319 t:(86-21)61196300 f:(86-21)61191853/68183920 e sgs.china@sgs.com