

**Project: Intercontinental Koh Yao Yai, Krabi**  
**PN: 19 01 DC**

**PRO AS2**

## Air+Surface Sterilizer

**Product name:** Air+Surface Sterilizer PRO AS2

**Product Description:**

The device is used for continuous 24/7 treatment for spaces up to 450sq ft to eradicate persistent indoor pollutants such as mould, odours and bacteria.

**Product Finishes:** Grey, Stainless Steel

**Supplier Name:** Medklinn International Sdn Bhd

**Contact:** Mr. Daniel Lu - commercial@medklinn.com

**Address:** No. 22, Jalan Pengacara U1/48, Tesmaya Industrial Park, 40150 Shah Alam, Selangor, Malaysia.

**Website:** [http://www.medklinn.com/my/business\\_solutions](http://www.medklinn.com/my/business_solutions)

**Indicative Price:** USD400 – USD517

**Annual Maintenance Cost:** approx. 15% of the product price

**Return On Investment:** 1 to 2 years

Item	Qty.
Model: PRO AS2	
RWG-25.....	1 Ea.
RWG-41.....	1 Ea.



\*This photo is not to scale

## Product Specification

Ozone Output (max)	20 mg/hr	Coverage Area	450 ft <sup>2</sup> / 48m <sup>2</sup>
Adjustable Ozone Output	Yes	Installation	Wall mount
Casing	Stainless Steel	Settings	Low / Mid / High / iKlinn
Negative Ion Emission Rate	>2 million /cm <sup>2</sup> per second	Dimension (mm)	172 (W) x 54 (D) x 137 (H)
Interchangeable Cartridge	Yes	Operating Environment	Temperature: 10°C- 35°C
Cartridge Option	Hybrid / Ozone	Oxygen Flow Rate	N/A
Power Plug Type	N/A	Number of outlets	N/A
Input Voltage	110-240 VAC	Tubing type	N/A
Input Current (max)	0.5 A	Weight	1.1kg
Power Consumption	<7 W	Maintenance parts(s)	Cartridge and Fan




## Wall mount

1. Recommended installation height is at least 2m from the floor.
2. The device needs a minimum clearance of 0.6m from any object (eg. ceiling, walls, cabinets, lightings, etc.) and at least 2m from return air vents.
3. Install device in a well ventilated area (preferably near supply) and away from direct sunlight.

## Some of our customers

Pullman	Grand Hyatt
Novotel	Hilton
The Fullerton	Intercontinental
Peninsula	HardRock
Cititel	Doubletree By Hilton
Mandarin Oriental	ParkRoyal
St Regis	Holiday Inn
Sheraton	Genting Grand
Le Meridien	@ Resort World Genting
Maxims @ Resort World	Crockfords @ Resort
Genting	World Genting



## References

**User Manual:**

[www.drive.google.com/drive/folders/1vn5qf8FaBRAq4i0N-E9dQ1kIMSTQE2lJ](http://www.drive.google.com/drive/folders/1vn5qf8FaBRAq4i0N-E9dQ1kIMSTQE2lJ)

**Test Reports:**

[www.drive.google.com/open?id=1TgRw6BWKsEP7KFD5wCCZpiz\\_edGmAAb0](http://www.drive.google.com/open?id=1TgRw6BWKsEP7KFD5wCCZpiz_edGmAAb0)

**Brochures:**

[www.drive.google.com/open?id=1h\\_hA3QH5m-VSMxg2r\\_u4SEjomTZPT9wq](http://www.drive.google.com/open?id=1h_hA3QH5m-VSMxg2r_u4SEjomTZPT9wq)

**Customer Testimonials:**

[www.drive.google.com/open?id=1Axu5WsyFQpEAMbi4t\\_vptXv1UHJzAyxB](http://www.drive.google.com/open?id=1Axu5WsyFQpEAMbi4t_vptXv1UHJzAyxB)

**Project Implementations:**

[www.drive.google.com/open?id=1hRrRuZVEHJ11Zrg-htw2xj-WwKLnsgqU](http://www.drive.google.com/open?id=1hRrRuZVEHJ11Zrg-htw2xj-WwKLnsgqU)