ใบรายงานผลการทดสอบการรับแรงกระแทก (Impact Energy Test)



Doc no. S0779A-14



Asian Institute of Technology

Km. 42 Paholyothin Highway, Klong Luang, Pathumthani, Thailand 12120

P. O. Box 4 Klong Luang, Pathumthani 12120 Thailand. Tel. (66-2) 524-5527, 524-6427 Fax. (66-2) 524-5544

STRUCTURAL ENGINEERING LABORATORY

STRUCTURAL ENGINEERING FIELD OF STUDY

SCHOOL OF ENGINEERING AND TECHNOLOGY

TYPE OF TEST:

DETERMINATION OF RESISTANCE TO STRUCTURAL DAMAGE BY MULTIPLE

IMPACTS FROM A LARGE SOFT BODY (BS5234: Part2: 1992 Annex E)

TEST SPECIMEN:

One (1) specimen of partition wall having a size of 3,000 x 2,400 x 150 mm., made of autoclaved aerated concrete "Smartblock G4" of size of 20 x 60 x 15 cm., was installed

by the client. The lintels of wall were installed at the height of 1.50 m.

CLIENT:

SMART CONCRETE PUBLIC CO., LTD.

DATE OF TEST:

December 16, 2014

TEST RESULTS:

Point No.	Number of Impact	Impact Energy (N.m)	Surface condition after tested
1	1	300	No crack was found on the specimen.
	2	300	No crack was found on the specimen.
	3	300	No crack was found on the specimen.

Note: 1) The impact energy of 300 N.m was produced from lifting the sand bag of weight 50 kg. with the drop height of 610 mm.

2) This report certifies the adequacy and representative character of the test sample(s) only.

TESTED BY:

MR. SAMWAI SORNSRIDA

MR. EKKACHAI YOOPRASERTCHAI

RESEARCH ASSOCIATE

TECHNICIAN

CHECKED BY:

APPROVED BY:

PROFESSOR PENNUNG WARNITCHAI FIELD COORDINATION OF STE/SET

January 9, 2015